APRIL 23, 1986



RE: CHEMICAL SPILL

3450 CALUMET AVE.

HAMMOND, INDIANA



Griffin Dewatering Corporation 3450 Calumet Avenue Hammond, IN 46320 219-931-1662 312-374-5255 Chicago

DEPT. OF ENVIRONMENTAL MANAGEMENT 1330 W. MICHIGAN ST. INDIANAPOLIS, IND. 46206

ATTN: MR. JOHN KASSIS (3,7) 243-5162

DEAR JOHN,

AS REQUESTED, I AM SUBMITTING THIS REPORT TO EXPLAIN THE CAUSE OF AND REMOVAL OF A SMALL CHEMICAL SPILL AT OUR HAMMOND, INDIANA FACILITY.

ON THE EVENING OF MONDAY, APRIL 14, 1986, ONE OF OUR MECHANICS WAS ADDING WATER TO A TANK THAT CONTAINS A PRODUCT CALLED CARB-GON, AS MANUFACTURED BY PENNWALT CORP. THIS IS A AUTOMOTIVE PARTS CLEANER THAT WE MIX ON A TWO (2) PARTS WATER TO ONE (1) PART PRODUCT BASIS. THE WATER WAS BEING ADDED THROUGH A GARDEN HOSE. WHEN HE TURNED THE WATER FAUCET OFF HE DIDN'T TURN IT OFF COMPLETELY. HE THEN WENT HOME FOR THE EVENING. THE FOLLOWING MORNING HE DISCOVERED THAT THE TANK HAD OVER FLOWED ONTO THE SHOP FLOOR, AND PARTIALLY COLLECTED AROUND A FLOOR DRAIN. HE IMMEDIATELY PLUGGED THE FLOOR DRAIN, AND THEN PULLED THE HOSE FROM THE TANK.

WHEN I ARRIVED AT WORK, I WAS INFORMED AS TO THE PRECEDING EVENTS. I HAD MY PEOPLE "MOP-UP" THE REMAINING LIQUID AND PUT IT IN AN EMPTY 55 GALLON DRUM. WE THEN REMOVED THE FLOOR DRAIN PLUG, BUT THE DRAIN APPEARED EMPTY. WE IMMEDIATELY CHECKED THE OUTLET END OF THE DRAIN PIPE AND FOUND A SMALL AREA OF DISCOLORATION IN THE ROAD DITCH, IN FRONT OF OUR FACILITY.

AT THIS POINT, WE FIGURED THAT THE AMOUNT OF LIQUID THAT ESCAPED THROUGH THE DRAIN WAS PROBABLY IN THE RANGE OF TWO HUNDRED GALLONS (200 GAL. ±). TO DETERMINE THIS, WE WENT BACK TO THE WATER HOSE (WHICH WAS STILL RUNNING) AND MEASURED THE VOLUME COMING THROUGH IT. THE VOLUME WAS ABOUT FIFTEEN GALLONS PER HOUR (15 GPH). THE ELAPSED PERIOD FROM 5:00 PM THE NIGHT BEFORE TO 8:00 AM THAT MORNING WAS FIFTEEN (15) HOURS. THIS MEANT THAT APPROXIMATELY TWO HUNDRED AND TWENTY-FIVE (225) GALLONS HAD OVERFLOWED. THE LIQUID THAT THEY "MOPPED-UP" FILLED ABOUT ONE-HALF (½) OF A 55-GALLON DRUM; THEREFORE, THE REMAINING LIQUID WAS IN THE TWO HUNDRED (200) GALLON RANGE.

RE: CHEMICAL SPILL 3450 CALUMET AVE. HAMMOND, INDIANA



THE AREA OF RUSTY DISCOLORATION, IN THE ROAD DITCH, WAS ABOUT TWELVE FEET (12') ACROSS AND TWENTY FEET (20') LONG. THIS MEANT THAT THE TWO HUNDRED (200) GALLONS WAS THINLY FLOATING ON TOP OF THE DITCH WATER. WE FELT THAT THIS SMALL AMOUNT OF NON-FLAMMABLE LIQUID WOULD BE DILUTED SO QUICKLY THAT IT WOULD, FOR ALL INTENTS AND PURPOSES, DILUTE AND EVAPORATE WITH THE DITCH WATER.

WE WOULD LIKE TO NOTE THAT WE HAVE BEEN IN BUSINESS AT THIS LOCATION SINCE 1967, AND THAT WE FELT THIS SMALL DILUTION WAS OF MINOR CONSEQUENCE IN COMPARISON TO WHAT IS ALREADY IN THESE DITCHES ALONG CALUMET AVENUE, NEXT TO AMOCO OIL COMPANYS' WHITING REFINERY AND TANK FIELDS.

ON FRIDAY, APRIL 18, WE WERE CONTACTED BY THE LOCAL FIRE DEPART-MENT REGARDING THE DISCOLORATION IN THE DITCH. IN FACT, THE DISCOLORATION WAS A VERY LIGHT, RUSTY TINT THAT HAD COVERED THE TOP OF MOST OF THE WATER SURFACE IN FRONT OF OUR FACILITY. THE DITCH IS TWO HUNDRED AND NINETY FEET (290') BETWEEN CULVERTED DRIVEWAYS, AND TWELVE FEET (12') ACROSS AT THE TOP.

WE INFORMED THE FIRE DEPARTMENT THAT THE LIQUID HAD NO FLASH POINT AND THAT IT WAS A METAL CLEANER. THEY, OF COURSE, CONTACTED YOU AND TOLD US 10 DO THE SAME.

UPON YOUR RECOMMENDATION WE SECURED A COUPLE OF LARGE TANKS AND SET-UP A PUMPING SYSTEM TO SKIM THE DILUTED LIQUID FROM THE DITCH WATER. ON MONDAY, APRIL 21, WE PROCEEDED TO PUMP THE LIQUID INTO THESE TANKS, WHICH WE LOCATED BEHIND OUR BUILDING IN OUR STORAGE YARD. AFTER FILLING TWO (2) OF THE TANKS, WE OBSERVED THE "NORMAL" COLORATION IN THE DITCH WATER, AND WE TERMINATED PUMPING. WE THEN MEASURED THE LIQUID IN THE TANKS, WHICH ADDED UP TO SEVEN THOUSAND ONE HUNDRED (7100) GALLONS.

OUR INTENTION IS TO REUSE THIS LIQUID AS WE NEED IT.

IF I CAN ANSWER ANY FURTHER QUESTIONS, PLEASE CALL ME AT (219/931-1662).

VERY TRULY YOURS, GRIFFIN DEWATERING CORP.

JOE HOCKBERGER BRANCH MANAGER

ENCLOSURE



DATA

We have moved & our new address is:

DOLPHIN INCORPORATED 5609 MURVIHILL ROAD

VALPARAISO, IN 46383

3880

April 22, 1986

.€0	• •	

MATERIAL SAFETY DATA SHEET -EMERGENCY TELEPHONE NO. SECTION (219) 465-1808 ١, TRADE NAME AND SYNONYMS GENERAL Metal Cleaner 1718 **FORMATION** CARB-GON FORMULA CHEMICAL FAMILY TRADE SECRET Chlorinated Hydrocarbon PROPOSED USES: NA - Not Applicable NE - Not Established PRINCIPAL HAZARDOUS COMPONENT(S) SECTION , CASE TLV (units)* (CHEMICAL & COMMON HAME(S)) WT_WT. 11 IAZARDOUS IGREDIENTS 100 ppm 75-09-2 Methylene Chloride 1319-77->9 Cresylic Acid 5 ppm . 3 64742-Aromatic Hydrocarbon >5 50 ppm 9405 SPECIFIC SOLUBILITY SECTION BOILING 100-212^oF IN WATER GRAVITY 1.16 POINT NE Ш PHYSICAL pH OF VAPOR PERCENT 90 NE DATA PRESSURE VOLATILES SOLUTION VAPOR EVAPORATION Slower than ether >1DENSITY RATE (Air = 1) **PHYSICAL** FORM/ODOR AUTO IGNITION METHOD | D Clevland Open Cup SECTION FLASH POINT □ TAG ☐ Closed Cup TEMP NA NONE IV FIRE LOWER EXPLOSION **EXTINGUISHING** Water Fog - Dry Chemical - Foam NE UMIT MEDIA AND **EXPLOSION** Self contained breathing apparatus LIMIT SPECIAL FIRE NE DATA FIGHTING PROCEDURES UNUSUAL FIRE & NOTE DECOMPOSITION PRODUCTS EXPLOSION HAZARDS SECTION DI STABLE CONDITIONS CONTRIBUTING TO INSTABILITY HAZARDOUS POLYMERIZATION CONTAMINATION O UNSTABLE O THERMAL DECOMPOSITION REACTIVITY D PHOTOSENSITIVE DEGRADATION

INCOMPATABILITIES - MATERIALS/CONDITIONS TO AVOID:

MATERIALS: ME ACIOS I ALKALIS ME OXIDIZERS/REDUCERS IN WATER IN OTHER (SPECIFY)

CONDITIONS: ME HEAT POTENTIAL MOPEN FLAME OF SPARKS OF IGNITION SOURCES OF OTHER (SPECIFY)

Hydrogen chloride, carbon monoxide, trace phosgene

SECTION	MHRESHOLD LIMIT VALUE 100 ppm (est)	PHIMARY HOUTES OF EXPOSURE	M Skin Contact N Eye Contact	M Skin Absorption M Inhelation	() Ingestion		
HEALTH	NATURE & BITE OF EFFECTB/FIRST AID PROCEDURES	<u>.</u>		in the president section of the sect	Minimum negati, apos a apos des 190 e 191 m. in final		
HAZARD	MIN OF ACUTE O CHRONIC O IRRITANT OF CORROSIVE () SENSITIZER O OTHER (SPECIFY)						
DATA	WASH AFFECTED AREA & REMOVE CONTIM	INATED GLOTHING () SEE	K IMMEDIATE ME	DICAL ATTENTION			
	occomme Medical Instalment Flush area with soap and water. May be absorbed through skin and mucous membranes. Seek medical attention if irritation persists.						
· .	EYES M ACUTE () CHRONIC () IRRITANT & CORROSIVE () OTHER (SPECIFY)						
	M FLUSH WITH WATER FOR 15 - MINUTES A SEEK IMMEDIATE MEDICAL ATTENTION						
	DESCRIBE MEDICAL TREATMENT						
		•					
	RESPIRATORY C. ACUTE N. CHRONIC D. IRRITANT			<u> </u>			
	() ACOTE & CANONIC () INNITARY		i	,			
	o sensitizer of hemove to fresh beschille medical attention. M headache, nausea, e	ay cause anes			-		
		anger same same					
	INGESTION			D. (50.50.5)			
	NE ACUTE , CI CHRONIC () IRRITANT ME CORROSIVE () TARGET ORGANS (SPECIFY) () OTHER (SPECIFY) NE DO NOT INDUCE VOMITING () INDUCE VOMITING () ADMINISTER WATER/MILK () MESSEEK IMMEDIATE MEDICAL ATTENTION						
	i '	NG D ADMINISTER WATE	H/MICK W SEE	K IMMEDIATE MEDICA	LAHENHON		
	DESCRIBE MEDICAL TREATMENT						
	<u> </u>		. 1.		<u> </u>		
	MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE NONE			*			
	CHEMICAL LISTED AS CARCINOGEN OR POTENTIAL CARCINOGEN NONE	NATIONAL TOXICOLI PROGRAM		ONOGRAPHS D NO	OSHA D YE		
	1 N E	THRESHOLD NE T VALUE		HER EXPOSURE LIMIT USED	NE		
SECTION	IS VENTILATION REQUIRED : 정 YES □ NO 및 GE	ENERAL ŒLOCAL T	o maintai	n below TLV			
VII	EYE PROTECTION: X YES IN NO I GOGGLES I FACE SHIELD OF OTHER Safety glasses						
SPECIAL	RESPIRATORY PROTECTION. 18 YES 1 NO 18 GA	S/VAPOR D PARTICULAT	e Organi	c vapor			
*ROTECTION **FORMATION	HAND PROTECTION (GLOVE): Ø YES 🗆 NO 🗆 CLOTH 💢 LEATHER 💢 IMPERMEABLE 🗀 PVC 🗖 NATÚRAL RUBBER						
	D POLYETHYLENE & NEOPRENE D POLYVINYL ALCO	HOL D BUTYL RUBBER (OTHER (SPECIF)	n :			
	OTHER PERSONAL PROTECTIVE EQUIPMENT: W YES C	Rubbe	rized out	er garment			
	(PLEASE SPECIFY)			العاد الله المدارية المساكم ما يعالمها	• •		
· 							
SECTION	& WASH THOROUGHLY AFTER HANDLING	(J STORE IN DIKE	D AREA			
VIII	M KEEP AWAY FROM HEAT, SPARKS & OPEN FLAME		DO NOT BREAT	HE DUST, VAPOR, MIS	T, GAS		
HANDLING	Ø EMPTY CONTAINER MAY CONTAIN HAZARDOUS RES ☑ STORE IN WELL VENTILATED AREA		DO NOT STORE	NEAR COMBUSTIBLE	s		
AND	Ø DO NOT GET IN EYES, ON SKIN OR CLOTHING	C	STORAGE AREA	SHOULD BE POSTED)		
STORAGE	O STORE IN TIGHTLY CLOSED CONTAINERS	C	J TRANSPORTATIO	ON PRECAUTIONS (SP	ECIFY)		
	SEEP FROM CONTACT WITH CLOTHING & OTHER CO		OTHER (SPECIF	n Release			
	Pressure from container slowly						
SECTION	D FLUSH WITH WATER	NEUTRALIZE WITH					
	전 KEEP UPWIND: EVACUATE ENCLOSED SPACES _ □	SWEEP OR SCOOP UP A	ND REMOVE TO				
SPILL OR LEAK	A ABSORB WITH SAND OR INERT MATERIAL DISPOSE OF IMMEDIATELY DIOTHER (SPECIFY)						
RESPONSE	O PREVENT SPREAD OR SPILL W	ASTE DISPOSAL METHOO:	8 INCINERATION	D APPROVED LANDE	ILL O OTHER		